24 April 1962

Declass Review by NIMA/DOD

	MEMORANDUM FOR THE RECORD	
5X1A	SUBJECT: Electronic Rectifier	25X1A
	REFERENCES: (a) Memorandum for the Record from dated 10 April 1962; same subject] 25X1A
	(b) Memorandum for from Chief, TID, dated 12 April 1902; same subject	25X1A
5X1A	(c) Telephone conversation between In-House Maintenance Representative, and Major TP & DS, on 17 April 1902	
5X1A	said that ESPA, AMS, needed the outside dimension of the rectifier's shielded enclosure for planning the installation of both rectifiers in Abert Hall, the new AMS building. He also wanted to know who would pay for the move and for a change in design so that the door and the service panel would be on the short (14') side instead of the present long (18') side.	ns
5X1A	2. was told that the shielded enclosure could be modified to meet about any requirements, but that the matter of funding would have to be decided jointly among ESPA, NPIC and the NPIC Army Element.	
	3. The present status of the rectifier/shielded enclosure matter is as follows:	25X1A
	a. The architects for the new buildings for ESPA and NPIC are both planning space, power and air conditioning requirements on the basis that they will get both rectifiers (one belonging to TID/NPIC and the other belonging to the Army Element) in their respective buildings.	
	b. No rectifier tapes have been produced to date and, as a result, no rectified material has been produced to date.	
	c. Mr. Lundahl has expressed an interest in the rectified material (See reference (b) above.)	·25X1A
5X1A		
5X1A	NAIC/TR&DS:	

2